



# IECEX Quality Assessment Report

<b>QAR Reference No.</b>	DE/BVS/QAR06.0014/10	<b>Status</b>	Current
<b>QAR Free Ref. No.</b>	ZQS/E185/17		
<b>Audit Date</b>	<b>Date of issue</b>	<b>Valid until</b>	
2016-12-06	2016-12-20	2020-02-12	
<b>Detail of change</b>	Introduction of ISO 9001:2015		
<b>Site(s) audited</b>	Kirchgaesser Industrieelektronik GmbH,Am Rosenbaum 6,40882 Ratingen,GERMANY		
<b>Issuing ExCB</b>	BVS - DEKRA EXAM GmbH		
<b>Manufacturer</b>	Kirchgaesser Industrieelektronik GmbH,Am Rosenbaum 6,40882 Ratingen		
<b>Country of Manufacture</b>	Germany		
<b>Product information</b>	Manufacture and distribution of measuring, control and monitoring instruments for mining and industry		
<b>Protection concept</b>	Intrinsic safety "i",Optical radition "op is/pr/sh",Protection by enclosure "t"		
<b>Related QARs</b>	DE/BVS/QAR06.0014/10 DE/BVS/QAR06.0014/09 DE/BVS/QAR06.0014/08 DE/BVS/QAR06.0014/07 DE/BVS/QAR06.0014/06 DE/BVS/QAR06.0014/05 DE/BVS/QAR06.0014/04 DE/BVS/QAR06.0014/03 DE/BVS/QAR06.0014/02 DE/BVS/QAR06.0014/01 DE/BVS/QAR06.0014/00		
<b>Related Certificates (manual insertion)</b>	None		
<b>Related IECEx Certificates</b>	<b>ExCB</b> ▼ BVS IECEX BVS 07.0010 issue: 0 IECEX BVS 07.0010 issue: 1 IECEX BVS 07.0010 issue: 2 IECEX BVS 07.0010 issue: 3 IECEX BVS 07.0010 issue: 4 IECEX BVS 08.0004X issue: 0 IECEX BVS 08.0004X issue: 1 IECEX BVS 11.0016 issue: 0 IECEX BVS 11.0016 issue: 1 ▼ TSA IECEX TSA 11.0043X issue: 0 IECEX TSA 14.0005X issue: 0		
<b>Comment</b>	None		
<b>Annexes</b>	<a href="/iecex/iecexweb.nsf/0/E833D41A85DFE924C125809000325582/\$file/">(/iecex/iecexweb.nsf/0/E833D41A85DFE924C125809000325582/\$file/)</a>		